Huawei single phase L1 inverters

	Device comms port		L1 comms port	Note
Smart meter	25 (B)	\rightarrow	3	CT white to 5,
	24 (A)	→	4	blue to 6
Battery	7	→	3	
	4	→	4	
	2	\rightarrow	5	
	3	→	6	
1P Backup Box	1 on X4	\rightarrow	8	Shunt between 4
	2 on X4	\rightarrow	5	and 5 on X2
Cascading with L1 inverters	1	→	1	
	2	→	2	
Cascading with M1 inverters	1	→	2	
	3	\rightarrow	1	

Huawei three phase M1 inverters

	Device comms port		M1 comms port	Note
Smart meter	25 (B)	→	9	CT white to 13,
	24 (A)	→	7	16, 19, blue to
				rest
Battery	7	\rightarrow	9	
	4	\rightarrow	7	
	2	\rightarrow	13	
	3	\rightarrow	11	
3P Backup Box	1 on X4	\rightarrow	8	Shunt between 4
	2 on X4	\rightarrow	16	and 5 on X2
Cascading with L1 inverters	1	→	3	
	2	\rightarrow	1	
Cascading with M1 inverters	1	→	1	
	3	\rightarrow	3	